

Speedthane Spring 'Rubbers'



NEW Nominal Rate Increases

4 ½ - 5 ½ Inch Rear Spring 'Helpers' double groove

MLRSA-130	softest	red	10
MLRSA-148	medium	white	15
MLRSA-167	stiff	blue	20
NEW MLRSA-185	Stiffer	Yellow	30

STD + Mini Coilover Spring Helpers double groove

COSA-43 /MCO-24	softest	red	5
COSA-49/ MCO-27	medium	white	10
COSA-57/MCO-32	stiff	blue	15
NEW COSA-62	Stiffer	Yellow	20

With all the new rule changes, we are responding with a new rate spring helper, to keep YOU on top of the competition.

Important: These rates are good starting places. Each spring combination needs to be rated. A number of factors can influence the rate you see: 1. Location in the spring, (middle, top, bottom), 2. Installed height of the spring. 3. Coil spacing often differs between different manufacturers for the same rate spring.